

# SFP-P モータ・減速機対応表 (TCGカタログP.71)

作成日：2024.6.17

※削除部(赤塗り箇所)

安川電機 YASKAWA Electric

の型式は減速機加速時トルクを超えないようにご注意ください。

モータ型式			SFP型式・減速比																
			SFP70				SFP85				SFP100				SFP125				
			8	10	20	30	10	20	30	40	10	20	30	40	10	20	30	40	50
Σ-X	SGMXJ	01A	A0308	A0308	A0308	A0308	C0208	C0208	C0208	C0208									
		C2A	A0308	A0308	A0308	A0308	C0208	C0208	C0208	C0208									
		02A	B0214	B0214	B0214	B0214	C0414	C0414	C0414	C0414	E0214	E0214	E0214	E0214	F0214	F0214	F0214	F0214	F0214
		04A	B0214	B0214	B0214	B0214	C0414	C0414	C0414	C0414	E0214	E0214	E0214	E0214	F0214	F0214	F0214	F0214	F0214
		06A	B0214	B0214	B0214	B0214	C0414	C0414	C0414	C0414	E0214	E0214	E0214	E0214	F0214	F0214	F0214	F0214	F0214
		08A									E0619	E0619	E0619	E0619	F0419	F0419	F0419	F0419	F0419
	SGMXA	01A	A0308	A0308	A0308	A0308	C0208	C0208	C0208	C0208									
		C2A	A0308	A0308	A0308	A0308	C0208	C0208	C0208	C0208									
		02A	B0214	B0214	B0214	B0214	C0414	C0414	C0414	C0414	E0214	E0214	E0214	E0214	F0214	F0214	F0214	F0214	F0214
		04A	B0214	B0214	B0214	B0214	C0414	C0414	C0414	C0414	E0214	E0214	E0214	E0214	F0214	F0214	F0214	F0214	F0214
		06A	B0214	B0214	B0214	B0214	C0414	C0414	C0414	C0414	E0214	E0214	E0214	E0214	F0214	F0214	F0214	F0214	F0214
		08A									E0619	E0619	E0619	E0619	F0419	F0419	F0419	F0419	F0419
	SGMXG	09A									G0224	G0224	G0224	G0224	G0224	G0224	G0224	G0224	G0224
		13A									G0224	G0224	G0224	G0224	G0224	G0224	G0224	G0224	G0224
		20A									G0224	G0224	G0224	G0224	G0224	G0224	G0224	G0224	G0224
	Σ-7	SGM7J	01A	A0308	A0308	A0308	A0308	C0208	C0208	C0208	C0208								
			C2A	A0308	A0308	A0308	A0308	C0208	C0208	C0208	C0208								
			02A	B0214	B0214	B0214	B0214	C0414	C0414	C0414	C0414	E0214	E0214	E0214	E0214	F0214	F0214	F0214	F0214
04A			B0214	B0214	B0214	B0214	C0414	C0414	C0414	C0414	E0214	E0214	E0214	E0214	F0214	F0214	F0214	F0214	F0214
06A			B0214	B0214	B0214	B0214	C0414	C0414	C0414	C0414	E0214	E0214	E0214	E0214	F0214	F0214	F0214	F0214	F0214
08A											E0619	E0619	E0619	E0619	F0419	F0419	F0419	F0419	F0419
SGM7A		01A	A0308	A0308	A0308	A0308	C0208	C0208	C0208	C0208									
		C2A	A0308	A0308	A0308	A0308	C0208	C0208	C0208	C0208									
		02A	B0214	B0214	B0214	B0214	C0414	C0414	C0414	C0414	E0214	E0214	E0214	E0214	F0214	F0214	F0214	F0214	F0214
		04A	B0214	B0214	B0214	B0214	C0414	C0414	C0414	C0414	E0214	E0214	E0214	E0214	F0214	F0214	F0214	F0214	F0214
		06A	B0214	B0214	B0214	B0214	C0414	C0414	C0414	C0414	E0214	E0214	E0214	E0214	F0214	F0214	F0214	F0214	F0214
		08A									E0619	E0619	E0619	E0619	F0419	F0419	F0419	F0419	F0419
		10A									E0619	E0619	E0619	E0619	F0419	F0419	F0419	F0419	F0419
15A														F0624	F0624	F0624	F0624	F0624	
SGM7P		01A	B0208	B0208	B0208	B0208	C0408	C0408	C0408	C0408									
		02A					D0214	D0214	D0214	D0214	E0514	E0514	E0514	E0514	F0414	F0414	F0414	F0414	F0414
		04A					D0214	D0214	D0214	D0214	E0514	E0514	E0514	E0514	F0414	F0414	F0414	F0414	F0414
SGM7G		03A																	
	05A																		
	09A													G0224	G0224	G0224	G0224	G0224	
	13A													G0224	G0224	G0224	G0224	G0224	
	20A													G0224	G0224	G0224	G0224	G0224	

# NSP モータ・減速機対応表 (TCGカタログP.89)

※修正部 (赤文字箇所)

富士電機 FUJI Electric

モータ型式			NSP型式・減速比					
			NSP32A		NSP32C		NSP40C	
			19	39	19	39	19	39
ALPHA7	GYS	202D7	A0324	A0324	A0324	A0324		
		302D7	A0428	A0428	A0428	A0428	D0128	D0128
		402D7	A0428	A0428	A0428	A0428	D0128	D0128
		502D7	A0428	A0428	A0428	A0428	D0128	D0128
	GYG	132B7	A0522	A0522	A0522	A0522	D0222	D0222
		182B7	<b>A0522</b>	<b>A0522</b>	<b>A0522</b>	<b>A0522</b>	<b>D0222</b>	<b>D0222</b>
		152C7	A0422	A0422	A0422	A0422	D0122	D0122
		202C7	A0422	A0422	A0422	A0422	D0122	D0122
ALPHA5	GYS	202D5	A0324	A0324	A0324	A0324		
		302D5	A0428	A0428	A0428	A0428	D0128	D0128
		402D5	A0428	A0428	A0428	A0428	D0128	D0128
		502D5	A0428	A0428	A0428	A0428	D0128	D0128
	GYG	132B5	A0522	A0522	A0522	A0522	D0222	D0222
		152C5	A0422	A0422	A0422	A0422	D0122	D0122
		202C5	A0422	A0422	A0422	A0422	D0122	D0122

# RGU モータ・減速機対応表 (TCGカタログP.105)

※削除部 (赤塗り箇所)

安川電機 YASKAWA Electric

※リングユニットの最大使用トルクを超えないようにご使用ください。

モータ型式		RGU型式・減速比									
		RGU1610A-				RGU2510A-					
		C40-40	C40-80	C40-120	C40-160	C40-40	C40-80	C40-120	C40-160	C40-200	
		C60-60	C60-120	C60-180	C60-240	C50-50	C50-100	C50-150	C50-200	C50-250	
		C80-80	C80-160	C80-240	C80-320	C60-60	C60-120	C60-180	C60-240	C60-300	
		C100-100	C100-200	C100-300	C100-400	C70-70	C70-140	C70-210	C70-280	C70-350	
		C240-240	C240-480	C240-720	C240-690	C125-125	C125-250	C125-375	C125-500	C125-625	
		C300-300	C300-600	C300-900	C300-1200	C150-150	C150-300	C150-450	C150-600	C150-750	
						C190-190	C190-380	C190-570	C190-760	C190-950	
Σ-X	SGMXJ	01A			C0208						
		C2A		C0208	C0208	C0208					
		02A		C0414	C0414	C0414					
		04A	C0414	C0414	C0414	C0414				F0214	F0214
		06A						F0214	F0214	F0214	F0214
		08A						F0419	F0419	F0419	F0419
	SGMXA	01A				C0208					
		C2A		C0208	C0208	C0208					
		02A		C0414	C0414	C0414					
		04A	C0414	C0414	C0414	C0414				F0214	F0214
		06A						F0214	F0214	F0214	F0214
		08A						F0419	F0419	F0419	F0419
	SGMXG	09A					F0419	F0419	F0419	F0419	F0419
		09A					G0224	G0224	G0224	G0224	G0224
	Σ-7	SGM7J	01A			C0208					
			C2A		C0208	C0208	C0208				
			02A		C0414	C0414	C0414				
			04A	C0414	C0414	C0414	C0414				F0214
06A								F0214	F0214	F0214	F0214
08A								F0419	F0419	F0419	F0419
SGM7A		01A				C0208					
		C2A		C0208	C0208	C0208					
		02A		C0414	C0414	C0414					
		04A	C0414	C0414	C0414	C0414				F0214	F0214
		06A						F0214	F0214	F0214	F0214
		08A						F0419	F0419	F0419	F0419
		10A					F0419	F0419	F0419	F0419	F0419
		15A					F0624	F0624	F0624	F0624	F0624
SGM7P		01A				C0408					
		02A	D0214	D0214	D0214	D0214					
		04A	D0214	D0214	D0214	D0214				F0414	F0414
SGM7G		03A									
		05A									
		09A					G0224	G0224	G0224	G0224	G0224